DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-006388

Address: 333 Burma Road **Date Inspected:** 26-Apr-2009

City: Oakland, CA 94607

OSM Arrival Time: 1730 **Project Name:** SAS Superstructure **OSM Departure Time:** 700 Prime Contractor: American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai, China

CWI Name: CWI Present: Yes Liu Ming and Chen Ying Xin No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes N/A **Delayed / Cancelled:** No

Bridge No: 34-0006 **Component:** Tower and OBG

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance Inspector (QA) Joe Alaniz was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

This QA inspector performed UT of approximately 10% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated an UT report for this date. The member(s) is/are identified as North Tower Lift 3 Skin D. The weld designations reviewed are as follows:

Bay 10

- 1. NSD1-FBAS3-3B/C-5A/B and 6A/B
- 2. NSD1-FBAS3-3A/C-28A/B and 29A/B

This QA Inspector observed the following work in progress:

SAW welding of weld joint 2A located on PCMK ESD1-A167B/H.

Welder is identified as Mr. Xu Xiushui (040489). ZPMC QC is identified as Mr. Liu Ming.

The welding variables recorded by QC appeared to comply with WPS-B-T-2221-B-U3c-S-2.

WELDING INSPECTION REPORT

(Continued Page 2 of 3)

FCAW welding of weld joint 139 located on PCMK NSD1-A166H/J.

Welder is identified as Mr. Yu Jun (201825). ZPMC QC is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-2333-Tc-P4-F.

FCAW welding of weld joint 9 and 8 located on PCMK NSD1-A166F/J.

Welder is identified as Mr. Xu Xiuping (057244). ZPMC QC is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-4133.

FCAW welding of weld joint 143 and 145 located on PCMK NSD1-A112E/H.

Welder is identified as Mr. Bai Wen Ming (040434). ZPMC QC is identified as Mr. Chen Ying Xin.

The welding variables recorded by QC appeared to comply with WPS-B-T-2333-Tc-P4-F.

Bay 11

FCAW welding of weld joint 9 located on PCMK ESD1-SA107B/J.

Welder is identified as Mr. Xu Hua (049220). ZPMC QC is identified as Mr. Xu Le Feng.

The welding variables recorded by QC appeared to comply with WPS-B-T-4132.

SMAW welding of weld joint 6A located on PCMK WD1-A467-43M-1.

Welder is identified as Mr. Xie Zhong Cheng (041271). ZPMC QC is identified as Mr. Xu Le Feng. The welding variables recorded by QC appeared to comply with WPS-345-SMAW-2G (2F)-FCM-Repair-1

Bay 13

This QA Inspector observed the following work in progress:

SAW welding of weld joint 001 located on PCMK SEG047B.

Welder is identified as Mr. Zhang Min (215993). ZPMC QC is identified as Mr. C.M Chen.

The welding variables recorded by QC appeared to comply with WPS-B-T-2221-B-L2c-S-2.

Bay 9

This QA Inspector observed ZPMC welder Han Hongwen (200149) welding (repair) on Deck Panel DP394-001(9CE) in OBG Assembly Shop (Bay 9). QC Inspector was not present at the time of work. QA Inspector issued an incident report on this date for the welding observed.

WELDING INSPECTION REPORT

(Continued Page 3 of 3)

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang (134-8257-0045), who represents the Office of Structural Materials for your project.

Inspected By:	Alaniz,Joe	Quality Assurance Inspector
Reviewed By:	Carreon, Albert	QA Reviewer